Handling Tools: Product Bulletins Index

Handling Tools PIBs

Document Number	Rev	Date Released	Product Line	Title	Description	Affected Assemblies	PIB Type
STRAP-161-PIB-001	01	04/24/2015	Handling Tools	Elevator Balancing Strap failure	ELEVATOR BALANCING STRAP FAILURE	Oracle part number 10019468-001, legacy part number 15320.	Safety Alert
BJ-160-PIB-001	01	04/24/2015	Handling Tools	VAILABILITY OF LANYARD	VAILABILITY OF LANYARD KITS FOR YOKE PIN.	part numbers starting with 5000XXX, or produced after 2008	Product Information Bulletin
BX/LINKS-153-PIB-001	02	04/24/2015	Handling Tools	INTERFERENCE BETWEEN BX4-75 ELEV	INTERFERENCE BETWEEN BX4-75 ELEVATOR AND 750T LINKS	BX4-75 elevator (50000650Y/Z/10034284-001) and 750T Links (16143Y/ZXXX/10490414-XXX)	Product Information Bulletin
PS21/30-156-PIB-001	02	03/25/2015	Handling Tools	Power Slip Maintenance	POWER SLIP MAINTENANCE AND CONTROL	legacy part numbers 202200-% and 202400-%	Product Information Bulletin
SSD-159-PIB-001-PIB-001	01	03/05/2015	Handling Tools	Potential pinch points	POTENTIAL PINCH POINTS ON SIDE DOOR ELEVATORS	part numbers 71273 thru 71277 and 71994	Product Information Bulletin
SPLIT BOWL-157-PIB-001	01	02/09/2015	Handling Tools	Indications on welds	INDICATIONS ON WELDS OF SPLIT BOWLS, WHICH CAN RESULT IN A POTENTIAL DROPPED OBJECT	Part numbers 6608-%, 6609 and 6610	Product Information Bulletin
BX4-155-PIB-001	01	11/19/2014	Handling Tools	Product enhancements on BX4	SUBJECT: PRODUCT ENHANCEMENTS ON BX4 ELEVATORS.	BX4-50 and BX4-75 hydraulic elevators	Product Information Bulletin
SJX-154-PIB-001	01	07/15/2014	Handling Tools	DROPPED OBJECT FROM A SJX SINGLE	DROPPED OBJECT FROM A SJX SINGLE JOINT ELEVATOR. (REF. TRACKER TICKET NOV-390693)	P/N's: starting with 50004929Y, 50004931Y, 50004933Y & 50004935Y	Product Information Bulletin
BX-149-PIB-001	01	03/04/2014	Handling Tools	Incorrect retainer bolt	INCORRECT RETAINER BOLT INSTALLED IN BX5. (REF. TRACKER TICKET NOV-404608)	BX3, BX4-35, BX5 & BX7 all serial numbers BX4-50 & BX4-75 serial number NL0112880 and below	Safety Alert
AOP-151-PIB-001	01	03/04/2014	Handling Tools	DROPPED PIPE INCIDENT WHEN USING	DROPPED PIPE INCIDENT WHEN USING HYC AIR OPERATED ELEVATOR	P/N 70166Y*(HYC), 35636Y* / 39343Y*(TA) 200035Y*(GA), 201380Y* (GGA), 36056Y* / 200574Y* (MGG), 35143Y*/200024Y* (GG), 70222Y* / 200059Y* (HGG)	Safety Alert
ES-152-PIB-001	01	03/04/2014	Handling Tools	Missing safety cable(s)	MISSING SAFETY CABLE(S).	All Varco types Elevator/Spider (500T, 750T and 1000T).	Product Information Bulletin
OEM-150-PIB-001	0	12/05/2013	Handling Tools	USE OF NON-OEM SLIPS IN	USE OF NON-OEM SLIPS IN NOV PRODUCTS	All NOV Original Equipment Manufacturer (OEM) products, using slips	Product Information Bulletin
BOREMATCH-148-PIB-001	01	10/24/2013	Handling Tools	Release of a new elevator/pipe	RELEASE OF A NEW ELEVATOR/PIPE SELECTION TOOL "BOREMATCH". RE-EMPHASIZE AVAILABILITY OF "PROFILE GAUGE".	"BoreMatch", part number 10710179-001. "Profile gauge" part number 10146201-001 (or legacy part number 59001005).	Product Information Bulletin
ES-147-PIB-001	01	10/24/2013	Handling Tools	INCORRECT INSERT INFORMATION, US	INCORRECT INSERT INFORMATION, USER MANUAL 10694078 REV.02 (HYDRAULIC E/S) AND 50000825-MAN-001 (PNEUMATIC E/S) REV B AND DOWN	P/N's: 70734Y5 / 10490446-005.	Safety Alert
D63-BX-146-PIB-001	01	05/29/2013	Handling Tools	Collision of the BX elevator	Collision of the BX elevator with the fingerboard and diving board.	203300YXX, 50000640Y, 50000650Y and 50004000YXX	Safety Alert
SLIPS-145-PIB-001	01	03/25/2013	Handling Tools	Potential hand injury when using	POTENTIAL HAND INJURY WHEN USING HAND SLIPS	All hand slips, type SDS, SDML, SDXL, SDHL, CMS-XL, DCS, UC-3 and UC-4 equipped with cast handle. (pn 3765, 3766, 3767, 3768 and 7704-A-17). Hand slips with forged and flex handles are excluded from this bulletin.	Safety Alert
BX-144-PIB-001	01	03/18/2013	Handling Tools	Potential dropped object	POTENTIAL DROPPED OBJECT RELATED TO WRONG BX LATCH VALVE ADJUSTMENT.	All NOV BX elevators equipped with latch valve 50003960-11.	Product Information Bulletin
ADAPTER-143-PIB-001	01	03/18/2013	Handling Tools	POTENTIAL PINCH POINTS ON FMS375	POTENTIAL PINCH POINTS ON FMS375 ADAPTER RING	All NOV FMS375 adapter rings part no.'s: 200990-11, 200991-11, 200995-11, 201430-1 and 202244-1	Product Information Bulletin
VARCO-ES-142-PIB-001	01	12/04/2012	Handling Tools	Dropped string with Varco type E	DROPPED STRING WITH VARCO TYPE ELEVATOR/SPIDER (13800Y)	All Varco Type Elevator/Spiders	Safety Alert
D841004380-PIB-001	03	05/01/2012	Handling Tools	DROPPED OBJECT INCIDENT INVOLVIN	DROPPED OBJECT INCIDENT INVOLVING A 400T AIR OPERATED ELEVATOR	400T Air Operated Solid Body Elevator (P/N 88471)	Safety Alert
D63FMS375-141-PIB-001	01	04/10/2012	Handling Tools	Potential of dropping bottom	POTENTIAL OF DROPPING BOTTOM GUIDES FROM VARCO TYPE E/S AND FMS375	All Varco Type Elevator/Spiders and FMS375	Safety Alert
79000739	0	03/06/2012	Handling Tools	ADDING PROXIMITY SENSORS ON STAN	ADDING PROXIMITY SENSORS ON STANDBUILDING ELEVATOR- ELEVATOR HEAD	Please see attached excel-list for specific projects.	Product Information Bulletin
D63OEM-140-PIB-001	01	11/16/2011	Handling Tools	THIS SAFETY BULLETIN ADDRESSES:	THIS SAFETY BULLETIN ADDRESSES: (A) NON-ORIGINAL EQUIPMENT MANUFACTURER PARTS AND/OR UNATHORIZED PRODUCT ENHANCEMENTS, MODIFICATIONS	Please see attached excel-list for specific projects.	Product Information Bulletin
D63SJH-139-PIB-001	01	11/16/2011	Handling Tools	DROPPED PIPE WHEN USING SJH TYPE	DROPPED PIPE WHEN USING SJH TYPE JOINT ELEVATOR	Please see attached excel-list for specific projects.	Safety Alert
D63-X-SERIES-138-PIB-001	01	11/10/2010	Handling Tools	SJX type verification pin	SJX TYPE VERIFICATION PIN	All SJX type single joint elevators (P/N's: starting with 50004929Y, 50004931Y, 50004933Y & 50004935Y)	Safety Alert
D63-SDHL-SERIES-137-PIB-001	01	10/22/2010	Handling Tools~Force and Load Measurement	RECOMMENDED USE OF RATED SDHL OV	RECOMMENDED USE OF RATED SDHL OVER SDXL HAND SLIPS ON FLOATERS	All SDXL and SDHL hand slips.	Product Information Bulletin
TDS-09-17-PIB	A	10/05/2010	Top Drives~Handling Tools	ASSEMBLY AND MAINTENANCE OF AIR	Assembly and Maintenance of Air Swivel Assemblies	Air Swivel Assembly located on the Top Drive Drill Stem	Product Information Bulletin

Handling Tools PIBs

Document Number	Rev	Date Released	Product Line	Title	Description	Affected Assemblies	PIB Type
TDS-09-17-PIB	A	10/05/2010	Top Drives~Handling Tools	ASSEMBLY AND MAINTENANCE OF AIR	Assembly and Maintenance of Air Swivel Assemblies	Air Swivel Assembly located on the Top Drive Drill Stem	Product Information Bulletin
75078299	0	08/31/2010	Handling Tools	UNDESIRED TORQUE WRENCH ROTATION	UNDESIRED TORQUE WRENCH ROTATION/CREEP DURING SPINNING TRAVEL OPERATIONS CAN BE STOPPED BY CHANGING OF THE SPOOL IN HAWE VALVE SECTI	Hydra Tool Frame TF-975 with SW-10 Spinner	Product Information Bulletin
D63-BX-136-PIB-001	01	08/18/2010	Handling Tools	Availability of the New Improved	AVAILABILITY OF THE NEW IMPROVED DESIGN BX TYPE ELEVATOR LATCH CYLINDER, DOOR CYLINDER AND MANIFOLD	Assemblies starting with 203300,203290, 203200, 50004000 and 50000202	Product Information Bulletin
D614000669-PIB-001	01	07/06/2010	Top Drives~Handling Tools	DROPPED OBJECT INCIDENT INVOLVIN	DROPPED OBJECT INCIDENT INVOLVING SUPPORT ARM PIN	Support Arm Pin (P/N 2031277)	Safety Alert
D63-BX5-134-PIB-001	01	03/24/2010	Handling Tools	Final Update to National Oilwell	FINAL UPDATE TO NATIONAL OILWELL VARCO (NOV) SAFETY ALERT PRODUCT INFORMATION BULLETIN NO¿S. 129, 131 & 132; DROPPED PIPE INCIDENT	All BX5 Hydraulic Elevators (P/N: 50004000Y10 & 50004000Y30)	Safety Alert
D63BX5-132-PIB-001	01	03/03/2010	Handling Tools	UPDATE TO NOV SAFETY ALERT PIB	Update to National Oilwell Varco (NOV) Safety Alert Product Information Bulletin No¿s. 129 and 131; Dropped Pipe Incident Involving a BX5 Elevator with Square Shoulder Riser Bushings.	All BX5 Hydraulic Elevators (part nos. 50004000Y30 & Y10)	Internal Bulletin
D63-BX4-133-PIB-001	01	02/26/2010	Handling Tools	BX ELEVATOR CAPACITIES	BX ELEVATOR CAPACITIES	All BX4-50 and BX4-75 elevators and casing, drill pipe, drill collar and riser bushings.	Product Information Bulletin