RELEASE NOTES

	Product	Version	Release Date	Changes	Descriptions
SPS	SPS2	3.21	2/28/2017	Bug Fixes	• Fixes undesired power down of the sensor pack by the debounce routines monitoring the sensor power line
		3.20	9/17/2014	Bug Fixes	• Fixes memory wrap issues • Corrects Battery 2 reporting
		3.10	11/26/2013	New Features/ Enhancements	• Changes Shock and Vibration calculations to prevent data from being kept at 45G
		1.03	4/9/2013	Bug Fixes	• Fixes issue with logging +/-13.5V and internal current • Fixes Bat1 and Bat2 current readings for background noise • Fixes issue with switching on/off the +/-13.5V