


RELEASE NOTES

	Product	Version	Release Date	Changes	Descriptions
	iSDU	4.44	2/28/2017	Fixes	<ul style="list-style-type: none"> Update to detect and correct memory logging issue (log pointer error)
		4.43	12/16/2015	Fixes	<ul style="list-style-type: none"> Minor bug fixes
		4.40	12/03/2014	Improvements/ Fixes	<ul style="list-style-type: none"> Improved smoothing of flow switch values Fix for sporadic pulse width graphing issue Uses improved firmware libraries for log corruption detection
		4.30	4/15/2014	Improvements/ Fixes	<ul style="list-style-type: none"> Fixed time/date stamp issue causing fragmented logging and failure to download data with Tool Tracker Restructured interrupt routines to help reduce latency. This deficiency was found in fixing bug above Improved current profile (OPTIMIZED/UNKNOWN/ FAIL) detection Removed "Magic Numbers" and harmonized all values into #defines to improve code support
		4.20	9/10/2013	Fixes	<ul style="list-style-type: none"> Minor bug fixes
		4.10	6/5/2013	New Features/ Fixes	<ul style="list-style-type: none"> Flow switch status tracking Shock and vibration standardization and enhancements Minor bug fixes
		4.06	8/28/2013	New Features	<ul style="list-style-type: none"> Shock and vibration standardization and enhancements Flow sensor status tracking Under the hood enhancements to data log retrieval
		4.05	8/28/2013	New Features	<ul style="list-style-type: none"> Sleep mode for use on our TCT (Tolteq Compact Tool) line of products Live pulse Pull-Hold-Base current readings displayed in Tolteq Tool Tracker software



					<ul style="list-style-type: none">• Enhanced power detection to prevent data log corruption
--	--	--	--	--	-----------------------------------------------------------------------------------------------------------